COMFORT COLORS®




Comfort Colors[®] Color Blast Crewneck Sweatshirt 1545

- 9.5-ounce, 80/20 ring spun USA cotton/poly
- Made with 80% sustainable and fairly grow n USA cotton and sew n w ith USA cotton thread
- 1x1 rib knit on collar
- Double-needle neck, shoulders, armholes, cuffs and
- w aistband
- Tw ill-taped back neck
- Rolled forw ard shoulder
- Relaxed fit, side-seamed body
- Tw ill label

The pigment dye and Color Blast process infuses each garment with unique color and appearance. Please allow for variation.

CARE INSTRUCTIONS


Maximum Washing Temperature 30C, Inside Out, With Like Colors. Only Oxygen/Non Chlorine Bleach Allow ed. Tumble Dry At Low Temperature, Max 60C. Do Not Iron. Do Not Dry Clean.



WWWWWWW

back

HOW TO MEASURE



CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms dow n, keeping tape horizontal.

SIZE CHART

	S	М	L	XL	2XL	3XL
Chest	37-45 1/2	41-47 1/2	45-50 1/2	49-53	53-56	56

COLOR INFORMATION

Please note: PMS code information is shown only when an exact match is available.





PMS 7404C



PMS 1945C



PMS 2410C







Smoke PMS 2332C