# American Apparel

## 2001CVC



## \*\*


## CARE INSTRUCTIONS

Maximum Washing Temperature 30 C, Inside Out, With Like Colors. Only Oxygen/Nonchlorine Bleach Allow ed. Tumble Dry At Low Temperature, Max 60 C. Do Not Iron. Do Not Dryclean.





#### HOW TO MEASURE



### CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms dow n, keeping tape horizontal.

#### SIZE CHART

	S	М	L	XL	2XL
Chest	37-38	39-40	41-42	43-44	45-46

#### COLOR INFORMATION

Please note: PMS code information is shown only when an exact match is available.



Black