



OGIO® Origin Jacket. OE503




COTTON-RICH SOFTNESS
 STAY-COOL WICKING
 LAYERABLE WARMTH


- 8.1-ounce, 64/36 cotton/poly flatback knit
- OGIO heat transfer label for tag-free comfort
- Zip-through collar
- Exposed coil zipper w ith molded cord pull
- Stacked O heat transfers at center back
- Welded front zippered pockets w ith locking pulls
- O heat transfer at right pocket
- Raglan sleeves w ith welded, articulated elbow s
- O heat transfer at upper left sleeve
- OGIO binding at cuffs and hem
- Slight drop tail hem

CARE INSTRUCTIONS

Machine w ash cold w ith like colors. Remove promptly. Only non chlorine bleach w hen needed. Tumble dry low . Cool iron if needed. Do not dry clean



front



back

HOW TO MEASURE



CHEST WIDTH

Measure under the arm and around the fullest part of the chest w ith arms dow n, keeping tape horizontal.

SIZE CHART

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

COLOR INFORMATION



Aluminum Grey
 PMS COOL GRAY
 8C



Blacktop
 PMS BLACK C